Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC.
Well Operator: CONTINENTAL RESOURCES, INC.
Well Name: BOXCAR BUTTE SOUTH FEDERAL 1-26H

Field Name: SOUTH BOXCAR Well File #: 17483

Date Incident:7/16/2015Time Incident:13:30Facility ID Number:County:MCKENZIETwp:148Rng:102Sec:26Qtr:

Location Description:

Submitted By: NATE STANHOPE Received By:

Contact Person: NATE STANHOPE

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 15 Barrels 15 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Environmental Impacts:

Location soil

Action Taken or Planned:

Standing oil was sucked up and returned to tank on-site. All impacted location soil was removed.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 7/17/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill remained on location with the dikes. NDIC retains oversight.